

DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 19: Climb via JAC R-192 to cross KICNE INT/JAC 27 DME at or above 15000. Thence. . . .

. . . .via (transition) or (assigned route). Expect further clearance to filed altitude 10 minutes after departure.

IDAHO FALLS TRANSITION (ALPIN2.IDA): From over KICNE INT via IDA R-096 to IDA VOR/DME.
SWEAT TRANSITION (ALPIN2.SWEAT): From over KICNE INT via BPI R-299 to BPI VOR/DME, then via BPI R-080 to SWEAT INT.

NW-1, 31 DEC 2020 to 28 JAN 2021
NW-1, 31 DEC 2020 to 28 JAN 2021