

COLNS TRANSITION (COLNS.GAVNN5):
HENDERSON TRANSITION (HNN.GAVNN5):

From GAVNN on track 310° to KNEDY, then on track 310° to AAJAY, then on track 006° to BACAS, then on track 006° to OGIRE.


LANDING SOUTH: Expect RADAR vectors to final approach course prior to OGIRE.

LANDING NORTH, EAST, WEST: Expect RADAR vectors to final approach course prior to AAJAY.

LOST COMMUNICATIONS:

At OGIRE fly heading 270°, maintain 6000; intercept and execute ILS RWY 18L approach. If unable, proceed direct to CVG VORTAC and hold NE. RT. 241° inbound, maintain 6000.

At KNEDY fly heading 270°, maintain 6000; intercept and execute ILS RWY 36R approach. If unable, proceed direct to CVG VORTAC and hold NE, RT, 241° inbound maintain 6000.



NOTE: RADAR required.

NOTE: RNAV 1.

NOTE: DME/DME/IRU or GPS required.

NOTE: Chart not to scale.