

PONTIAC, MICHIGAN

Diagram illustrating a flight path (likely a mission profile) starting from TORRR and proceeding through various waypoints and airports.

Waypoints and Airports:

- TORRR (Start)
- HEVYD (Waypoint)
- HAZIT (Waypoint)
- PETTE (Waypoint)
- SYREN 4000 (Waypoint)
- Ldg all Airports (Waypoint)
- ANN ARBOR MUNI (Airport)
- WILLOW RUN (Airport)
- CUSTER (Airport)
- GROSSE ILE MUNI (Airport)
- WINDSOR (Airport)
- COLEMAN A YOUNG MUNI (Airport)
- OAKLAND/TROY (Airport)
- OAKLAND COUNTY INTL (Airport)
- SELFREDGE ANGB (Airport)
- LIVINGSTON COUNTY SPENCER J HARDY (Airport)

Flight Path Details:

- TORRR to HEVYD: 10000, 045° (31)
- HEVYD to HAZIT: 10000, 037° (38)
- HAZIT to PETTE: 5000, 061° (21)
- PETTE to SYREN 4000: 5000, 089° (33)
- PETTE to Ldg all Airports: 10 NM, 241°
- Ldg all Airports to SYREN 4000: 4000, 072° (11)
- SYREN 4000 to Ldg all Airports: 4000, 025°
- Ldg all Airports to SYREN 4000: 4000, 071°

Notes:

- NOTE: RADAR required.
- NOTE: RNAV 1.
- NOTE: DME/DME/IRU or GPS required.
- NOTE: Caution: Parachute jumping 6 NM northeast of PETTE WAYPOINT, 3 NM radius of NAPOLEON AIRPORT (3NP) at or below 17999 (SR-SS).
- NOTE: QBURT TRANSITION: Do not file, to be assigned by ATC only.

NOTE: RADAR required.
NOTE: RNAV 1.
NOTE: DME/DME/IRU or GPS required.
NOTE: Caution: Parachute jumping 6 NM northeast of PETTE WAYPOINT, 3 NM radius of NAPOLEON AIRPORT (3NP) at or below 17999 (SR-SS).
NOTE: QBURT TRANSITION: Do not file, to be assigned by ATC only.

NOTE: Chart not to scale.

ARRIVAL ROUTE DESCRIPTION

HOSSA TRANSITION (HOSSA.PETTE2):
 QBURT TRANSITION (QBURT.PETTE2):
 TORRR TRANSITION (TORRR.PETTE2):
 WWODD TRANSITION (WWODD.PETTE2):

LANDING CYQG, KONZ, KARB, KYIP, KTTF, KDET: From PETTE on track 072° to cross SYREN at or above 4000, then on track 071°. Expect RADAR vectors to final approach course.

LANDING KPTK, KMTC, KOZW, KVLL: From PETTE on track 072° to cross SYREN at or above 4000, then on track 025°. Expect RADAR vectors to final approach course.