

RNAV (GPS) RWY 24

APCH CRS 243°	Rwy Idg 4100 TDZE 1161 Arpt Elev 1261
------------------	---

AL-2335 (USAF)

INDIAN MOUNTAIN LRRS (PAIM)



MISSED APPROACH: Climbing left turn to 7000 direct CHAZY and hold. Continue climb in hold to 7000.

ANCHORAGE CENTER
124.6 352.0

CTAF
126.2

FAIRBANKS RADIO
122.6


DME/DME RNP -0.3 NA

AWQS-3

Night operations
not authorized.

MILITARY CERTIFIED
AIRCRAFTS OR
AUTHORIZED CONTRACT
AIRCRAFT ONLY

NOT FOR CIVIL USE



CAUTION: Terrain 960 ft
MSL, 200 ft from threshold,
200 ft left of course.

Uncontrolled airspace below
700' AGL within 4 NM of
Indian Mountain airport.

EMERG SAFE ALT 100 NM 9900



VGSI and descent angles
not coincident (VGSI
angle 4.00/TCH 40).



PAPI beyond 8° right
of RCL unusable.

FATUR

ELEV 1261

TDZE 1161

Take-off Rwy 6
Land Rwy 24



CATEGORY	A	B	C	D
LNAV MDA	2360-1¼ 1199 (1100-1¼)	2360-1½ 1199 (1100-1½)	NA	

C CIRCULING

NOT AUTHORIZED

REIL Rwy 24