

ILS or LOC RWY 36
EPPLEY AIRFIELD (OMA)

MISSED APPROACH: Climb to 2000 then climbing right turn to 3000 direct OVR VORTAC and hold.

Knots	60	90	120	150	180
Min:Sec	4:36	3:04	2:18	1:50	1:32