

APP CRS	Rwy Idg	9803
285°	TDZE	143
	Apt Elev	143

RNAV (RNP) Z RWY 28

BALTIMORE/WASHINGTON INTL THURGOOD MARSHALL (BWI)

▼

For uncompensated Baro-VNAV systems, procedure NA below -12°C (11°F) or above 54°C (130°F). GPS Required. For inoperative MALSR, increase RNP 0.30 all Cats visibility to 1¼.

MALSR

MISSED APPROACH: Climb to 2500 on track 285° to COLUM and hold.

D-ATIS	POTOMAC APP CON	BALTIMORE TOWER	GND CON	CLNC DEL
115.1 127.8	(020°-100°) 119.7 290.475 (131°-180°) (101°-130°) 128.7 307.9 (181°-019°)	119.4 257.8	121.9	118.05

MISSED APCH FIX 4 NM

ELEV 143

D

TDZE 143

Procedure NA for arrivals at RAVNN on V379 westbound.

Procedure NA for arrivals at BILIT on V308 eastbound.

2500

COLUM

JURTI 2000

HURTZ 2000

RW28

285°

2000

GP 3.00°

TCH 55

CATEGORY	A	B	C	D
RNP 0.30 DA	521 / 45	378 (400-7%)		

AUTHORIZATION REQUIRED

BALTIMORE, MARYLAND  
Amdt 1 04FEB16

BALTIMORE/WASHINGTON INTL THURGOOD MARSHALL (BWI)  
39°11'N-76°40'W

RNAV (RNP) Z RWY 28