

ILS or LOC RWY 15

MALSR

MISSED APPROACH: Climb to 2000 then climbing right turn to 3000 direct AGJ VORTAC and hold.

HIRL Rwy 15-33

ELEV 1015 TDZE 1015

153° 5.8 NM from FAF

TWR 1191

GS 3.00° TCH 53

VGSI and ILS glide-path not coincident (VGSI Angle 3.00/ TCH 53).

***LOC only.**

CATEGORY	A	B	C	D	E
S-ILS #	1215/24		200 (200-½)		
S-LOC 15	1520/24 505 (600-½)	1520/55 505 (600-1)			
CIRCLING	1540-1 525 (600-1)	1560-1½ 545 (600-1½)	1620-2 605 (700-2)	1740-2½ 725 (800-2½)	
HOLD FIX MINIMUMS (DME REQUIRED)					
S-LOC 15	1380/24 365 (400-½)	1380/35 365 (400-¾)			
CIRCLING	1540-1 525 (600-1)	1560-1½ 545 (600-1½)	1620-2 605 (700-2)	1740-2½ 725 (800-2½)	

Knots: 60 90 120 150 180
Min:Sec: 5:48 3:52 2:54 2:19 1:56

SC-3, 03 DEC 2020 to 31 DEC 2020