

HUNTSVILLE INTL-CARL T JONES FIELD (HSV)

**MISSED APPROACH:** Climb to 2500 then climbing left turn to 4000 on heading 160° and VUZ R-011 to FEWER INT/VUZ 39.4 DME and hold.

ALTERNATE MISSED APCH FIX

ENIKY RQZ 23.7

1122 RQZ

R-195

Chan 59

015°

195°

Knots	60	90	120	150	180
Min:Sec	4:30	3:00	2:15	1:48	1:30

ILS or LOC RWY 18L