

ILS Y or LOC Y RWY 11
KETCHIKAN INTL (KTN)(PAKT)

MISSED APPROACH: Climb to 5000 direct CMJ NDB and on CMJ NDB bearing 124° to UCARU/I-ECH 6.6 DME and on ANNN VOR/DME R-338 to ANNN VOR/DME and hold.

#S-ILS 11 missed approach requires minimum climb of 305 feet per NM to 4000.

±S-ILS 11 missed approach requires minimum climb of 270 feet per NM to 4000.

S-LOC 11 missed approach requires minimum climb of 235 feet per NM to 4000.

If unable to meet climb gradients, see LOC X RWY 11.

129° 309°

(IAF) DOOZI ANN [40]

2742 2105 2600 4600 NoPT to RUYOC 124° hdg (2.9) and 115° (1.5)

(IF) RUYOC I-ECH [19.5]

3144 (CFCFZ) 4100 115° (5.6)

070° 250°

(IAF) COGOX I-ECH [13.9] ANN [30.3]

2000 1138 2300 2900

LOCALIZER 109.3 I-ECH [] Chan 30

CLAM COVE 396 GMJ []

3014 3383

647±A 2561 312 500 1003

OYECU I-ECH [4.8]

654 A 1755

ANNETTE ISLAND 117.1 ANN Chan 118

UCARU I-ECH [6.6]

2070

115° 12.5 NM from FAF

ELEV 92 TDZE 92

MISSED APCH FIX

NICHOLS 266 ICK []

ALTERNATE MISSED APCH FIX

KETCHIKAN, ALASKA KETCHIKAN INTL (KTN)(PAKT)
Amdt 8 10NOV16 55°21'N-131°43'W ILS Y or LOC Y RWY 1