

⚠

When local altimeter setting not received, use Smithfield altimeter setting and increase all MDAs 60 feet.
DME or RADAR required.

MISSED APPROACH: Climbing right turn to 2000 on heading 050° and ISO VORTAC R-302 to ESTER INT/ISO 14.5 DME and hold.

AWOS-3P 118.975	SEYMOUR JOHNSON APP CON ★ 123.7 290.9	UNICOM 122.7 (CTAF) 0
--------------------	--	--------------------------

2000	ISO R-302	ESTER INT	CRICK ISO 8 RADAR		
MAJAH ISO 20.5	COHAN ISO 16 RADAR	1600	2000		
4.5 NM	8 NM				
FAF to MAP 4.5 NM					
Knots	60	90	120	150	180
Min:Sec	4:30	3:00	2:15	1:48	1:30
CATEGORY	A	B	C	D	
CIRCLING	620-1 487 (500-1)	620-1¼ 487 (500-1¼)	620-1½ 487 (500-1½)	700-2 567 (600-2)	

GOLDSBORO, NORTH CAROLINA

Amtd 6 25AUG11

35°28'N-77°58'W

WAYNE EXECUTIVE JETPORT (GWW)

VOR-A