

WAAS CH <b>56623</b> <b>W32A</b>	APP CRS <b>323°</b>	Rwy Idg <b>5001</b> TDZE <b>20</b> Apt Elev <b>22</b>
--	------------------------	---

RNAV (GPS) RWY 32  
DESTIN EXECUTIVE (DTS)

<p><b>▼</b> Rwy 32 helicopter visibility reduction below ¾ SM NA. DME/DME RNP-0.3 NA. VDP NA when using Crestview altimeter setting not received, use Crestview altimeter setting and increase all MDA 80 feet; increase LP Cats C and D visibility ¼ SM, increase LNAV Cats C and D visibility ¾ SM, and increase Circling Cat C visibility ¼ SM.</p>	<p><b>MISSED APPROACH:</b> Climbing left turn to 2000 direct AJLIP and hold.</p>
--	--

ATIS <b>133.925</b>	EGLIN APP CON <b>132.1 360.6</b>	DESTIN TOWER ★ <b>118.45 (CTAF) 0</b>	GND CON <b>121.6</b>	CLNC DEL <b>121.6</b>	CLNC DEL <b>127.7 377.2</b> (When twr closed)	UNICOM <b>123.075</b>
------------------------	-------------------------------------	--	-------------------------	--------------------------	---	--------------------------

